

## **Advisory Alert**

**Alert Number:** AAA20241007 Date: October 7, 2024

Public Circulation Permitted | Public **Document Classification Level** 

**Information Classification Level** TLP: WHITE

## **Overview**

Product	Severity	Vulnerability
HPE	Critical	Remote Buffer Overflow Vulnerability
IBM	High, Medium, Low	Multiple Vulnerabilities
Cisco	Medium	Denial of Service Vulnerability

## **Description**

Affected Product	НРЕ
Severity	Critical
Affected Vulnerability	Remote Buffer Overflow Vulnerability (CVE-2021-38578)
	HPE has released security updates addressing a Remote Buffer Overflow Vulnerability that exists in HPE SimpliVity Servers.
Description	CVE-2021-38578 - Existing CommBuffer checks in SmmEntryPoint will not catch underflow when computing BufferSize.
	HPE advises to apply security fixes at your earliest to protect systems from potential threats.
Affected Products	<ul> <li>HPE SimpliVity 325 Gen 11 - Prior to HPE SimpliVity Gen11 Support Pack (SVTSP) v2024_0930</li> <li>HPE SimpliVity 380 Gen11 - Prior to HPE SimpliVity Gen11 Support Pack (SVTSP) v2024_0930</li> <li>HPE SimpliVity 170r Gen10 Server - Prior to HPE SimpliVity Gen10 Support Pack (SVTSP) v2024_0930</li> <li>HPE SimpliVity 190r Gen10 Server - Prior to HPE SimpliVity Gen10 Support Pack (SVTSP) v2024_0930</li> <li>HPE SimpliVity 2600 Gen10 - Prior to HPE SimpliVity Gen10 Support Pack (SVTSP) v2024_0930</li> <li>HPE SimpliVity 325 Gen10 - Prior to HPE SimpliVity Gen10 Support Pack (SVTSP) v2024_0930</li> <li>HPE SimpliVity 325 Gen10 Plus - Prior to HPE SimpliVity Gen10 Support Pack (SVTSP) v2024_0930</li> <li>HPE SimpliVity 380 Gen10 - Prior to HPE SimpliVity Gen10 Support Pack (SVTSP) v2024_0930</li> <li>HPE SimpliVity 380 Gen10 G - Prior to HPE SimpliVity Gen10 Support Pack (SVTSP) v2024_0930</li> <li>HPE SimpliVity 380 Gen10 H - Prior to HPE SimpliVity Gen10 Support Pack (SVTSP) v2024_0930</li> <li>HPE SimpliVity 380 Gen10 Plus - Prior to HPE SimpliVity Gen10 Support Pack (SVTSP) v2024_0930</li> <li>HPE SimpliVity 380 Gen10 Plus - Prior to HPE SimpliVity Gen10 Support Pack (SVTSP) v2024_0930</li> <li>HPE SimpliVity 380 Gen10 Plus - Prior to HPE SimpliVity Gen10 Support Pack (SVTSP) v2024_0930</li> </ul>
Officially Acknowledged by the Vendor	Yes
Patch/ Workaround Released	Yes
Reference	https://support.hpe.com/hpesc/public/docDisplay?docId=hpesbhf04716en_us&docLocale=en_US

Financial Sector Computer Security Incident Response Team (FinCSIRT)

TLP: WHITE	
12, CVE-2024-26671)	
exist in IBM QRadar and ited by malicious users to are and Arbitrary Code	
potential threats.	

TLP: WHITE

Affected Product	IBM
Severity	High, Medium, Low
Affected Vulnerability	Multiple Vulnerabilities (CVE-2024-6345, CVE-2024-45099, CVE-2024-45642, CVE-2024-26671)
Description	IBM has released security updates addressing multiple vulnerabilities that exist in IBM QRadar and IBM Storage Copy Data Management. These vulnerabilities could be exploited by malicious users to cause Denial of Service, Cross-site Scripting, Sensitive Information Disclosure and Arbitrary Code Execution.
	IBM advises to apply security fixes at your earliest to protect systems from potential threats.
Affected Products	IBM Security QRadar EDR version 3.12 IBM Storage Copy Data Management versions 2.2.0.0 - 2.2.24.0
Officially Acknowledged by the Vendor	Yes
Patch/ Workaround Released	Yes
Reference	<ul> <li>https://www.ibm.com/support/pages/node/7172419</li> <li>https://www.ibm.com/support/pages/node/7172212</li> <li>https://www.ibm.com/support/pages/node/7172211</li> </ul>

Affected Product	Cisco
Severity	Medium
Affected Vulnerability	Denial of Service Vulnerability (CVE-2024-20434)
Description	Cisco has released security updates addressing a Denial of Service Vulnerability that exists in Cisco Catalyst 9000 Series Switches.
	CVE-2024-20434 - Due to improper handling of frames with VLAN tag information, an attacker could send crafted frames to an affected device. A successful exploit could allow the attacker to render the control plane of the affected device unresponsive. The device would not be accessible through the console or CLI, and it would not respond to ping requests, SNMP requests, or requests from other control plane protocols. Traffic that is traversing the device through the data plane is not affected. A reload of the device is required to restore control plane services.
	Cisco advises to apply security fixes at your earliest to protect systems from potential threats.
Affected Products	Following products running on a vulnerable release of Cisco IOS XE Software (Use Cisco Software Checker to identify vulnerable versions)  Catalyst 9300LM Series Switches  Catalyst 9300X Series Switches  Catalyst 9400X Supervisor Engines  Catalyst 9500 High Performance Series Switches  Catalyst 9600 Series Switches
Officially Acknowledged by the Vendor	Yes
Patch/ Workaround Released	Yes
Reference	https://sec.cloudapps.cisco.com/security/center/content/CiscoSecurityAdvisory/cisco-sa-vlan-dos- 27Pur5RT

## Disclaimer

The information provided are gathered from official service provider's websites and portals. FinCSIRT strongly recommends members to apply security fixes as per the given guidelines, following the organization's patch and change management procedures to protect systems from potential threats.